

## 16 mm<sup>2</sup> CONNECTION TERMINALS FOR Cu - BUSBARS (SPRING)

**2140**

**2141**



CODE	DESCRIPTIONS	BOX PCS
2140	SK16 F 5 Connection Terminals For Cu Bar 1.5 - 16 mm <sup>2</sup>	100
2141	SK16 F 10 Connection Terminals For Cu Bar 1.5 - 16 mm <sup>2</sup>	100

## 35 mm<sup>2</sup> CONNECTION TERMINALS FOR Cu - BUSBARS (SPRING)

**2142**

**2143**



CODE	DESCRIPTIONS	BOX PCS
2142	SK35 F 5 Connection Terminals For Cu Bar 1.5 - 35 mm <sup>2</sup>	50
2143	SK35 F 10 Connection Terminals For Cu Bar 1.5 - 35 mm <sup>2</sup>	50

